

Site	Electrode	Source	SS	df	MS	<i>F</i>	<i>p</i> value
APSH	internal	factory calibration vs. single point error total	27.5 0.225 27.7	1 406 407	27.5 0.001	4.96E+04	< 0.001
APSH	external	factory calibration vs. single point error total	0.681 0.516 1.19	1 406 407	0.681 0.001	536	< 0.001
APSH	internal	factory calibration. vs. multi point error total	28.3 0.185 28.5	1 406 407	28.3 0.001	6.19E+04	< 0.001
APSH	external	factory calibration vs. multi point error total	0.692 0.521 1.21	1 406 407	0.692 0.001	539	< 0.001
APSH	internal	single point vs. multi point error total	0.005 0.143 0.148	1 406 407	0.005 0.000	15.0	< 0.001
APSH	external	single point vs. multi point error total	0.000 0.415 0.415	1 406 407	0.000 0.001	0.040	0.843